



### 23305NL

1/2" PEX F1807 No Lead Brass Ball Valve, Full Port



### EX23335NL

1-1/4" PEX F1960 No Lead Brass Ball Valve, Full Port



### 23322NL

3/4" PEX F1807 No Lead Brass Ball Valve, Full Port



### EX23341NL

1-1/2" PEX F1960 No Lead Brass Ball Valve, Full Port



### 23328NL

1" PEX F1807 No Lead Brass Ball Valve, Full Port



### EX23354NL

2" PEX F1960 No Lead Brass Ball Valve, Full Port



### 23335NL

1-1/4" PEX F1807 No Lead Brass Ball Valve, Full Port




### EX23822NL

3/4" PEX F1960 x 3/4" MNPT No Lead Brass Ball Valve



### 23341NL

1-1/2" PEX F1807 No Lead Brass Ball Valve, Full Port




### EX27241NL

1-1/2" PEX F1960 x 1-1/2" F/Sweat No Lead Brass Adapter



### 23354NL

2" PEX F1807 No Lead Brass Ball Valve, Full Port



### EX27254NL

2" PEX F1960 x 2" F/Sweat No Lead Brass Adapter



### 23822NL

3/4" PEX F1807 x 3/4" MNPT No Lead Brass Ball Valve



### EX23305NL

1/2" PEX F1960 No Lead Brass Ball Valve, Full Port



### EX23322NL

3/4" PEX F1960 No Lead Brass Ball Valve, Full Port



### EX23328NL

1" PEX F1960 No Lead Brass Ball Valve, Full Port

